

IPC Electronics Midwest 2010

Drop Testing of a Pb-Free Board after Assembly and SnPb-Rework

Eva Kosiba

Celestica

Biography:

Materials Lab Engineering Advisor

Eva graduated from the University of Toronto with a Bachelor of Engineering (Metallurgy and Material Sciences). She has over 10 years of experience at Celestica and is presently working in Performance Innovation Materials Lab. Previous roles at Celestica include Commodity Management, Supplier Quality Engineer and Project Manager of the Green Services™ team.

Contact Information

Eva Kosiba

Celestica

844 Don Mills Road

Toronto, ON M3C 1V7 Canada

416-443-7495 416-448-3029

ekosiba@celestica.com

Drop Testing of a Pb-Free Board After Assembly and SnPb-Rework




P. Snugovsky, J. Bragg, E. Kosiba, M. Thomson, B. Lee, R. Brush,
S. Subramaniam, M. Romansky
Celestica International Inc.

*A. Ganster, #W. Russell, **J. P. Tucker, **C. A. Handwerker, ##D.D. Fritz


***Crane NSWC, #Raytheon, **Purdue University, ##SAIC**

- Pb-free: reality for military applications due to part constraints
- Harsh environments have high mechanical reliability requirements
- Mechanical reliability concerns due to:
 - Greater functionality = higher I/O = smaller pitch size
 - Pb-free COTS interconnects prone to brittle fracture
 - Little known about the affect of rework
 - Even less known about rework of Pb-free joints with SnPb
- Robustness of electronics in harsh environments includes drop testing
 - Evaluate high strain and strain rate conditions

- Investigate specific need of the military
 - Mechanical shock robustness of non-BGA, Pb-free components reworked with SnPb solder
- Military prefers one rework solution in the field
- Simpler than controlling both SnPb and a Pb-free rework processes




- Board-level drop shock test was performed on 9 assemblies
 - 63 parts / board
 - Parts representative of military package styles
- Assembled on Pb-free compatible laminate with SAC 305 solder
- Selection of the non-BGA parts reworked with SnPb solder
- Metallurgical characterization
- Assemblies fixtured to drop table and subjected to 500Gs for a total of 20 drops
- In-situ shock response, net resistance and strain recorded
- Physical FA performed to characterize mechanical damage



- Test vehicle designed by:
 - Joint Group on Pollution Prevention (JG-PP)
 - National Aerospace Agency (NASA)
 - Department of Defense (DoD)
- Designed to meet IPC-6012, Class 3 requirements
 - 6 layer board with 0.5-ounce copper
 - Pb-free FR4 laminate as per IPC-4101/26
 - Minimum Tg of 170° C
 - Immersion Ag finish
- 9 assemblies selected for this rework study



Package	Ball or Finish	Dimensions (mm x mm)	Pitch (mm)	TV-Drop
PBGA225	SAC405	27 x 27	1.5	U02, U04, U04, U06, U18, U21, U43, U44, U55, U56
CSP100	SAC 105	10 x 10	0.8	U19, U32, U33, U35, U36, U37, U42, U50, U60, U63
→ TQFP-144	Matte Sn	20 x 20	0.5	U01, U03, U07, U20, U31, U34, U41, U48, U57, U58
→ TSOP-50	Sn	10.16 x 20.95	0.8	U12, U25, U29, U39, U61
	SnBi	10.16 x 20.95	0.8	U16, U24, U26, U40, U62
PDIP-20	NiPdAu	7.5 x 26.16	2.54	U8, U23, U49
	Sn	7.5 x 26.16	2.54	U11, U30, U38, U51, U59
→ CLCC-20	SAC305	9 x 9	0.8	U09, U10, U13, U14, U17, U22, U45, U46, U52, U53
→ QFN	Matte Sn	5 x 5	0.65	U15, U27, U28, U47, U54




CLCC-20

CANON COMMUNICATIONS LLC




TSOP-50

- Conductive, solder iron based rework on:
 1. TSOP
 2. TQFP
 3. CLCC (tack wrap procedure)
- Conductive processes as per IPC-7711:
 - Solder wicking & vacuum extraction
 - Heat, lift part, pad cleaning
 - Part placement & fluxing
 - Drag solder replacement & cleaning
- Convective, hot air rework for QFN devices




- Investigated metallurgy of 3 parts:
 1. TQFP (Cu lead frame)
 2. TSOP (alloy 42 lead frame)
 3. QFN (Cu lead frame)
- Investigated under 3 conditions:
 1. As-assembled SAC 305
 2. 1x rework with SnPb solder
 3. 2x rework with SnPb solder
- SEM / EDX was used to characterize intermetallics






Microstructure of SAC305 solder joints before rework (SEM 1000x)
LHS = TQFP (Cu), RHS = TSOP (alloy 42)

1x





2x




Microstructure of SAC 305 reworked using SnPb solder (SEM, 1000x)
LHS = TQFP (Cu), RHS = TSOP (alloy 42)

Intermetallic Thickness Before and After Rework






cs Industries




Drop Table with
Fixtured Test Vehicles

- Vast majority of electrical failures on PBGAs
 - Wide range in # of drops until failure
 - In-situ electrical **38%** (34/90) failed ≤ 5 drops
 - Suggests mechanical failure very few drops
 - **99%** (89/90) failed electrically after 20 drops
 - PBGA physical FA will be part of future work
- All 90 CSPs electrically passed drop testing
- 477 non-BGA components were tested
 - only **4 electrically** failed after 20 drops


- Only **4** non-BGA electrical fails (< 1%)
 - Board SN 84, CLCC-20, U14 was **not** reworked
 - Board SN 85, TQFP 144, U57 **was** reworked **once** with SnPb
 - Board SN 85, PDIP-20, U8 **was** reworked **once** with SnPb
 - Board SN 86, QFN-20, U15 **was** reworked **twice** with SnPb





Red = Mechanical failure – All pad craters
All BGAs are Electrically Failed
No leaded parts on this exact board electrically failed
Blue Dots on Some Parts = # of SnPb Hand Reworks


- Remaining 8 cards:
 - 23 parts dye & pried
 - 15 parts cross-sectioned
- Dye & pry and cross-sectioning was used to determine the:
 - Failure location
 - Failure mode, and
 - Failure mechanism
- Only non-BGA components were examined in this exercise




Solder Fracture,
Full Dye Penetration
(QFN, lead 2)




Pad Crater,
Partial Dye Penetration
(CLCC)




Solder Fracture
(TQFP-144, 1x rework)



Pad Crater with Trace Break
(CLCC)



Partial Solder Fracture
(QFN-20, 2x rework)



Partial Pad Crater
(QFN-20, 1x rework)

- Majority of non-BGA components survived drop testing
 - In-field rework of Pb-free parts with SnPb solder did not affect mechanical robustness
 - components reworked with SnPb solder are no less reliable than their Pb-free as-manufactured counterparts
- Both electrical and mechanical damage was at a minimum for non-BGA parts
 - Predominant failure mechanism was pwb-side pad cratering
- Electrical inspection not sufficient to assess mechanical robustness
 - ~1/3 of parts that passed electrical test had mechanical damage
- Drop testing showed early in-situ BGA electrical failures
 - mechanical damage may occur after only a few drops on BGAs

- Follow-on NASA DoD Pb-free projects:
 - Failure analysis of the BGAs
 - Drop testing on reworked BGAs
 - Results of ATC & vibration testing
 - Future drop testing of non-BGAs will employ a larger number of drops per board

The authors would like to thank the following individuals for assistance with the failure analysis:

- Jie Qian and Zohreh Bagheri (Celestica)

Thank You